



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES


MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 12/18/2014


Reviewed 

Mine Name: GR 200 Plus	Permit Number: S/019/0066	Mine Status: Active
Operator Name: GR 200 Plus, LLC	Inspection Date: 12/09/2014	Permit Fees: Delinquent
Inspector(s): M. Bradley	Inspection Time: 12:10pm	Bond Amount: \$27,100
Attendee(s): Solo	Weather: Pt. Cloudy, Cool	Bond Escalation: 07/16/2015
Inspection Purpose: Follow up from enforcement		Prior Inspection: 08/25/2014

Conclusions and Recommendations

Location: 572740.00 m E, 4308573.00 m N, UTM Zone 12N. Needed to check to see if reclamation had been performed as required through the CO issued in September, 2014. The CO provided a December 1, 2014 deadline for reclamation. A locked gate prevented access to the site directly, but the structures were visible from a point upstream along the Green River to indicate that no reclamation had taken place. In addition, the operator has not communicated with the Division, either verbally or in writing, to provide any status report on permit compliance or reclamation progress. The fact that the buildings were still in place and tops of gravel piles visible shows that reclamation has not been performed as required. It is recommended that a FTACO with an appropriate fine be sent to the operator and his agent.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
By failing to abate the conditions set forth in the CO issued in September, 2014, the permit remains out of compliance with inadequate reclamation surety in place.		
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Unabated conditions on site continue to pose a potential threat to public safety and welfare.		
3. <i>Protection of Drainages/Erosion Control</i>	<input type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i>	<input type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Reclamation has not been undertaken		
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Backfilling has not been undertaken		
8. <i>Soils</i>	<input type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Revegetation has not been undertaken		
10. <i>Other</i>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Chris Dunham, Dunham Farms; John Fasold, A. G. Cooper and Associates;

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M019-Grand/S0190066-GR200Plus/inspections/INSP-12092014.pdf



Locked gate approximately 1 mile from site



White buildings in left-center of image and tops of gravel piles near center of image indicating that no reclamation has been done.